

HOLSET

Turbo Parts

SEARCH: CTRL+F

***CW - Compress Wheel
TW - Turbine Wheel
BP - Backplate
BH - Bearing Housing
CHRA - Ce assembly
VNT - VNT Nozzle ring
ACT- Actuat
Heatshield***

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	2834153	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	2834289	HX35G	Tata Mots	BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	2834290	HX35G	Tata Mots	BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	2834949	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	2835181	HX40W	Cummins Inc.	ASIA MOT WKS	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3522879		3534947	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	2835549	HX35	Cummins Inc.	RAILCAR	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	2835695	HX35	Cummins Inc.	KOMATSU INDUSTRIAL	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	2837307				
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX30			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3539805		ND	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3502552	H2A	Perkins			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		3504344		3501502		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3502553	H2A	Perkins	MARINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		ND		3501502		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3502594	4LGK	Volvo	F12 - Truck		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		ND		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3502684	4LGK	Volvo			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		ND		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3503150	4LGK	Volvo	N10		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3502499		59618		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3500717						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3503327	4LGK	Scania	Truck - Bus		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59619		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3504220						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3504412	4LGK	Scania	Truck - Bus		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59619		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3504220						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3518213	H2A	Perkins			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		ND		3501502		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3519453	H1C	Onan	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3503945		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3520030	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3520055	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3520734	H1C	Baudouin	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3501502		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3521366	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3521457	HC3	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59619		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3500717						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3521525	H1C	Onan	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3503945		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3521743	4LGK	Volvo	TD121K		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		ND		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3521834	H1C				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3519216		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3522069	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3518200		3519336		3503945		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3522131	H2C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522773		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3522182	H1C	Sabre			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3522777	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3522778	H1C	JI Case			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3522883	H2C	Gardner	AUTOMOTIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3522951	H2C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523134	H2C	Iveco	180.24, 370.24 TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523223	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523228	H2C	Iveco	180.24, 370.24 TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523244	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523245	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523298	H2A	Perkins			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		ND		3501502		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523299	H2A	Perkins			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		ND		3501502		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523411	H2C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523519	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3590462		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523541	H1C	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523677	H1C	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3590462		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523718	H2C	Gardner	AUTOMOTIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504480		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523741	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3518200		3519336		3503945		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523742	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3518200		3519336		3503945		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3523744	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3524034	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3524035	H1E	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3524121	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3524122	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3524126	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3524129	H1E	Valmet			
CHRA			Repair Kit	-		Heatshield
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3522801						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3524312	H1C	Cummins Inc.			
CHRA			Repair Kit	-		Heatshield
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3590462		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3524427	H1C	Cummins Inc.			
CHRA			Repair Kit	-		Heatshield
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3524598	H2C	Renault			
CHRA			Repair Kit	-		Heatshield
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503304		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3524689	H1E	MAN	8.150 TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599645		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3526562						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3524695	H2C	Renault	G 290		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503304		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3524824	H2C	Perkins			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503305		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3524825	H2C	Perkins			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503305		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525094	4LGK	Iveco			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59619		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3504220						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525178	4LGK	Iveco	190.36, 330.36 TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3527176		59619		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3504220						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525196	4LGK	Iveco			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3527176		59619		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3504220						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525340	H1C	Cummins Inc.	MARINE-WET GENSET		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		ND		3524947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525341	H1C	Cummins Inc.	MARINE-WET GENSET		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		ND		3524947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525408	H2C	Volvo	F12, N12, NL12 TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525424	H1E	MAN			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525448	H2A	Iveco	AIFO		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519892		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525471	H1E	Valmet	Tract		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525472	H1E	Valmet			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525487	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525488	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525517	H2D	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525518	H2D	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525554	H1E	Sabre	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525648	H1C	Leyland Daf			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525670	H1C	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525689	H1E	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525692	4LGK	Iveco	CONSTRUCTION		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59618		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3504220						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525693	4LGK	Iveco	CONSTRUCTION		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59618		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3504220						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525700	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525711	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525721	H1C	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3525743	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3525826	H2D	Perkins	INDUSTRIAL	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3524997		3522773		62564	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3525199					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526008	H2D	Volvo		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3524997		3522773		62564	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3525199					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526009	H2D	Volvo		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3524997		3522773		62564	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3525199					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526025	H1E	MAN	TRUCK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599646		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3502500					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526032	H1E	Iveco	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526222	H2C	Iveco	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504480		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526369	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526401	H2D	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526466	H2D	Volvo	B10B, B10M TRUCK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3524808		3522773		62564	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3525199					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526488	H1E	Iveco	SNOWCAT	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599642		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3502500					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526576	H1E	Daewoo		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599646		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3526562					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526626	H1E	Cummins Inc.	MARINE	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599642		3525687		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530591					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526647	H2D	Iveco	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526740	H1C	Cummins Inc.	CHRYSLER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526829	H2D	Isotta Fraschini			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526886	H2D	Iveco	MARINE-PLEASURE BOAT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526887	H2D	Iveco	MARINE-PLEASURE BOAT	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3524808		3522773		62564	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3525199					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526923	H2D	Perkins	AUTOMOTIVE	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3524998		3522773		62564	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3525199					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526955	4LGK	Iveco	Truck - Bus	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3503704		3500433		59618	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3504220					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3526956	4LGK	Iveco	Bus	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3503704		3500433		59618	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3504220					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526963	H2D	Volvo	N12 TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		ND		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3526964	H2D	Volvo	FL12 TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3527018	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3527123	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3527220	H1E	Lister			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3527221	H1E	Lister			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599645		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3527222	H1E	Lister			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599645		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3527232	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3527887	H2D	Iveco			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3527997	H2D	Scania	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3527998	H2D	Scania	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528016	H2D	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528017	H2D	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528018	H2D	Scania	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528019	H2D	Scania	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528027	H2D	Iveco			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524998		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528088	H1E	Iveco			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528128	H2D	Iveco			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528129	H2D	Iveco	HARVESTER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528175	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528238	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528320	4LGK	Volvo	F12 - Truck		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59618		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3500717						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528321	4LGK	Volvo	TD121K		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59618		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3500717						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528328	4LGK	Volvo	TD100A		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3502499		59618		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3500717						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528353	H1E	Iveco	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528481	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528482	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528497	H1E	Tam Yugo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528622	H1E	Scania	92M TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528650	H2D	Scania	113 TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522773		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528651	H2D	Scania			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522773		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528704	H2D	Iveco			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3528709	H1E	Cummins Inc.	FREIGHTLINER	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599642		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530592					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3528740	H1C	Cummins Inc.		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3518200		3519336		3503945	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530591					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3528741	H1C	DFM	TRUCK & XMQ BUSES	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599639		3519336		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530591					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3528742	H1C	Cummins Inc.		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599639		3519336		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530591					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528743	H1C	JI Case			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528744	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528746	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528748	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528749	H1C	JI Case			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3590462		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528750	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3590462		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528752	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3518200		3519336		3503945		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528754	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528756	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528758	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528760	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3590462		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528762	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528764	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528766	H1C	Cummins Inc.	MARINE-WET GENSET		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		ND		3524947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528768	H1C	Cummins Inc.	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528770	H1C	Cummins Inc.	GENSET		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528772	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528774	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528777	H1E	JI Case			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528778	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528780	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528782	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528785	H1E	JI Case			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528786	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528788	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528790	H1E	DFM			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528791	H1E	JI Case			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528792	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528811	H2D	Volvo	NL12 TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528812	H2D	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528873	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528875	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528895	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528919	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528921	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528923	H1C	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528941	H2D	Scania	113 TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3528942	H2D	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529009	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529011	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529154	H1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3526562						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529155	H1E	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3526562						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529174	H2D	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529190	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529191	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529237	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529401	H2D	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529413	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529467	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529469	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529531	H2D	Scania			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529559	H2D	Volvo	B10M TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529620	WH1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3526562						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529661	H2D	MAN	TRUCK - ECO370/430		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529664	H2D				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529725	H2D	Perkins	ERF E12TX		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529840	H2D	Perkins			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524998		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3529872	H1E	Hino	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530001	H1E	Iveco			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530005	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530094	WH1E	MAN	17.272/23.272 TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530197	H2D	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524998		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530229	H2D	MAN			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524998		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530345	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530346	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530347	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530348	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530384	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530385	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530386	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530629	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530714	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530715	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530716	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530721	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530723	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530740	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530741	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		ND		3524947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530742	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530743	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530744	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530745	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530772	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530773	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530861	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530862	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530862	WH1E	JI Case			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530900	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530972	H2D	Hino	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530973	H2D	Hino	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530991	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530993	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530995	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3530997	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531027	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3525687		4027309		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531029	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531030	H1D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531031	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531032	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531033	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		ND		3524947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531034	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531035	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531038	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531039	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531040	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531152	H1C	Onan			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531153	H1C	Onan			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531199	H1E	Iveco	AGRICULTURAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3522879		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531272	H2D	Iveco	TRUCK-SPR RANGE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531363	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531369	H2D	Scania			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524998		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531377	H2D	Scania			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531388	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531504	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531505	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531653	H2C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531664	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531668	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531669	H2D	Iveco	370E30 BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531696	H1C	Leyland Daf			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531710	WH1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531711	WH1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531719	H2D	Scania	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531773	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531806	H2D	Sabre			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531810	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531811	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531812	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531836	H2E	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3528123		3522773		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533195						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531858	HX55				
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533542						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531883	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3531893	WH1E	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532034	H2D				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532042	HX35W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532153	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532202	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532223	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532297	H1E	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532345	H1C	Kamaz			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3519217		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532477	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532491	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532495	HX35W	Cummins Inc.	FD		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532496	HX35W	Cummins Inc.	FD		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532497	HX35W	Cummins Inc.	FD		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532498	HX35W	Cummins Inc.	FD		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532592	WH2D	Iveco	Genset		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528638						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532692	HX55				
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533542						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532739	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532740	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532741	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532939	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532965	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532966	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3532967	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533000	HX40				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533001	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533004	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533005	HX40				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533006	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533007	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3532632		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533008	HX40				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533009	HX40	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533011	HX40W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533012	HX40W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533014	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533015	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533020	4LGK	Scania			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59618		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3504220						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533040	WH1E	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533041	WH1E	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533042	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533054	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533055	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533057	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533058	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533060	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533061	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533087	H2D	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		6254		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528638						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533089	H2D	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		6254		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528638						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533103	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533122	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533133	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533303	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533304	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533305	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533306	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533307	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533308	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533310	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533311	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533312	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533313	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533314	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533315	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533317	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533319	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533321	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533364	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533365	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533366	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533367	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533368	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533369	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533370	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533371	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533372	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533373	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533374	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533375	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533376	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533521	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533564	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533577	H2D	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533617	H2D	Scania	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533618	H2D	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533697	HX40				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533690		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591794						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533730	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533731	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533733	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533734	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533736	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533737	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533739	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533740	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533741	WH1E	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533776	H2D	Perkins	Eagles		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528638						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533813	H2D				
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533878	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533879	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533880	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533901	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533902	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533903	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533904	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533905	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533906	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533907	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533908	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533917	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3533972	WH1E	JI Case			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534020	WH1E	Cummins Inc.	AGCO TRACT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534024	WH1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534027	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534098	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534205	H2D	MAN			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534237	WH1E	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534238	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534239	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534240	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534242	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534276	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528206						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534286	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534296	WH1C	Iveco			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3520574						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534298	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534369	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534370	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534372	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534374	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534376	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534378	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534408	WH1E	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3520574						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534453	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534470	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534474	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3519336		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534475	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534495	H1E	Iveco			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534529	HX35G	Cummins Inc.	GAS ENGINE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534530	HX35G	Cummins Inc.	GAS ENGINE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534531	HX35G	Cummins Inc.	GAS ENGINE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534608	HX35W	Cummins Inc.	CALIFNIA TLEV		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534609	HX35W	Cummins Inc.	CALIFNIA TLEV		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534610	WH1E	Cummins Inc.	AGCO TRACT		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534615	WH1E	Volvo			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3520574						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534616	WH1E	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3520574						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534619	WH1E	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3520574						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534665	H1E	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534666	H1E	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534830	H1C	Cummins Inc.	KOMATSU		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534876	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534918	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534919	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534920	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534922	HX35W	Cummins Inc.	FD		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534924	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534926	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534928	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534930	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534932	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534934	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534974	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534975	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534976	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534977	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534978	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534979	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534981	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534982	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534983	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534985	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3534996	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535002	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535004	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535005	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535059	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535088	WH1C	Iveco			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3520574						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535104	WH1E	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535112	WH2D	Iveco	Genset		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528638						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535118	H1C	DFM			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535204	WH1E	MAN	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535212	WH1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535269	H2C	Perkins			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503305		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535271	H2C	Perkins			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503305		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535273	H2D	Perkins			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524998		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3535275	H2D	Perkins			
CHRA			Repair Kit	-		Heatshield
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3535294	WH1C	Cummins Inc.			
CHRA			Repair Kit	-		Heatshield
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3535362	H1E	Yanmar			
CHRA			Repair Kit	-		Heatshield
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3535379	H2D	Perkins			
CHRA			Repair Kit	-		Heatshield
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535381	H1C	Jl Case			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535414	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535415	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535416	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535418	H1C	DFM	MILITARY TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535419	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535420	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535421	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535422	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535423	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535424	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535425	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535426	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535427	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535428	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535429	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535430	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535431	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535432	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535433	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535434	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535435	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535436	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535437	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535438	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3504649		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535439	H1C	Cummins Inc.	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535440	H1C	Cummins Inc.	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535441	H1C	Cummins Inc.	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535442	H1C	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		ND		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535443	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535444	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535445	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535446	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535447	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535448	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535449	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535450	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535451	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535452	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535453	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535454	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535456	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535457	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535458	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535463	HX50				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3534856		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533052						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535464	HX50				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3534856		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533052						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535534	H1E	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535535	H1E	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535536	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535536	H1E	DFM	TRUCKS & XMQ BUSES		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535537	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535539	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535540	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535541	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535542	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535543	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535546	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535547	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535548	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535549	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535550	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535551	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535576	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535577	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535578	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535579	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535580	H2D	Perkins			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535612	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535613	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535614	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535615	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535616	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535617	HX40W	JI Case	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535619	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535620	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535631	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535632	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535634	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535635	HX40W				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535636	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535638	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535664	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535665	HX40W	Cummins Inc.	FD CARGO TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535666	WH1C	Cummins Inc.	ELITE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535667	WH1C	Cummins Inc.	ELITE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535749	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535788	HX40W	Cummins Inc.	CASE 720 TRACT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535789	HX40W	JI Case	7250 TRACT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535789	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535790	HX40W	Cummins Inc.	7250 TRACT		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535791	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535792	HX40W	Cummins Inc.	CASE 7250 TRACT		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535797	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535819	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535821	H2D	Perkins			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524998		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535834	HX35W	Cummins Inc.	CHRYSLER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535871	WH1E	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535872	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535873	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3535972	WH1E	Volvo	FL7, FS7 TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3520574						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536028	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536043	H1E	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536045	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536046	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536047	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536051	WH1C	Cummins Inc.	ELITE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536056	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536065	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536066	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536115	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536116	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536119	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536120	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536121	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536122	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536160	HX35W	Cummins Inc.	1996 CHRYSLER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536161	HX35W	Cummins Inc.	1996 CHRYSLER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536178	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536213	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536215	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536217	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536219	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536244	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536245	WH1E	Cummins Inc.	HANOMAG		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536246	WH1E	Cummins Inc.	HANOMAG		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536272	H2D	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536296	HX40W				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536297	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3536298	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		Repair Kit HX40	-		Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3536299	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		Repair Kit HX40	-		Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3536304	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		Repair Kit HX40	-		Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3536306	HX40W	JI Case	INDUSTRIAL		
CHRA		Repair Kit HX40	-		Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536307	HX40W	JI Case	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536310	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536312	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536313	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536314	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536315	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536316	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536317	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3536318	HX35W	Cummins Inc.	OFF HIGHWAY	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3536319	HX35W	Cummins Inc.	1996 OFF HIGHWAY	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3536320	HX35W	Cummins Inc.	1996 OFF HIGHWAY	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3536321	HX35W	Cummins Inc.	1996 OFF HIGHWAY	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536322	HX35W	Cummins Inc.	1996 OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536323	HX35W	Cummins Inc.	1996 OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536324	HX35W	Cummins Inc.	1996 OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536325	HX35W	Cummins Inc.	1996 OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536326	HX35W	Cummins Inc.	1996 OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536328	HX35W	Cummins Inc.	1996 OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536330	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536331	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536332	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536334	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536335	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536339	HX35	Cummins Inc.	KOMATSU		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536341	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536345	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536349	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536350	HX40G	Cummins Inc.	CASE NEW HOLLAND		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536351	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536352	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536353	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536355	HX40G	Cummins Inc.	GAS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536356	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536421	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536470	HX35	TCL	HCV		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536472	HX35W	TCL	HCV		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536474	HX35	TCL	HCV		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536545	HX40W	Volvo	OLYMPIAN Mk II		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536611						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536565	H2D	Iveco	RAILWAY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536676	HX35G	Cummins Inc.	ION BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536677	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536678	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536679	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536680	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536681	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536682	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536684	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536685	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536686	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536687	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536688	H1E	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536713	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536714	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536715	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536720	H1E	Cummins Inc.	AUTOLATINA		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536722	H1E	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536724	WH1E	Cummins Inc.	HANOMAG		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536726	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536818	HX40	Cummins Inc.	SPECIALIST VEHICLES		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536915	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536915	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536972	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536973	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536974	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536975	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536976	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3536978	HX35W	Cummins Inc.	OFF HIGHWAY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537019	HX35	Komatsu	PC200,228UU		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537020	HX35	Cummins Inc.	KOMATSU		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537063	HX40W	Cummins Inc.	DEP		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537064	HX40W	Cummins Inc.	DEP		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537093	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537094	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537095	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537096	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537126	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537127	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537128	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537129	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537130	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537131	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537133	HX35	Cummins Inc.	ELITE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537134	HX35	Cummins Inc.	ELITE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537135	HX35	Cummins Inc.	ELITE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537136	HX35	Cummins Inc.	ELITE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537137	HX35	Cummins Inc.	ELITE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537190	H1C	Cummins Inc.	KOMATSU		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537203	HX40W	Cummins Inc.	FIREPUMP		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537234	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537238	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537245	HX50	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3531763		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4035125						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537246	HX50	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3531763		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4035125						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537248	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537249	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537250	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537251	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537252	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537254	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537256	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537257	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537258	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537259	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537260	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537262	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537264	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537265	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537266	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537267	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537268	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537270	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537285	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537287	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537288	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537289	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537290	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537291	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537292	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537293	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537294	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537303	WH1E	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537360	H1C	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537462	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537463	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537464	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537465	HX35	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537466	HX35	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537468	HX35	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537470	HX35W	Cummins Inc.	FD		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537471	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537472	HX35W	Cummins Inc.	FD		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537473	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537474	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537476	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537479	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537480	HX35W	Cummins Inc.	FD ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537481	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537482	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537484	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537496	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537497	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537498	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537499	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537500	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537512	HX40G	Cummins Inc.	GAS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537514	HX35G	Cummins Inc.	NATURAL GAS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537525	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594834		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537965						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537526	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594834		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537965						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537528	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537543	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537545	WH1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537546	WH1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537552	H1E	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537557	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537558	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537559	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537567	HX40W	Cummins Inc.	FIREPUMP		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537569	HX40W	Cummins Inc.	FIREPUMP		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537639	HX50				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3534287		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533052						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537662	H1C	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537671	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537672	HX40W	Cummins Inc.	1993/4 TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537761	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537766	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537785	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537786	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537840	HX55				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533542						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537884	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537885	HX40W	Cummins Inc.	FIREPUMP		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3537913	HX55				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX55			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533542						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538031	WH1E	MAN	TRUCK		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538032	WH1E	MAN	TRUCK		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538065	H2D	Liaz			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538072	H1E	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538120	HX40W	Cummins Inc.	300 ELITE INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538122	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538123	HX40W	Cummins Inc.	AGRICULTURAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538125	H1E	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538188	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538203	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538204	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538205	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538206	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538207	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538208	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538209	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538210	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538213	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538215	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538219	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538220	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538221	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538222	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538223	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538224	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538225	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538226	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538227	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538228	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538230	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538231	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538233	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538236	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538237	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538238	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538240	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538351	HX40W	Cummins Inc.	G-DRIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538352	HX40W	Cummins Inc.	G-DRIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538354	HX40W	Cummins Inc.	G-DRIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538355	HX40W	Cummins Inc.	G-DRIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538414	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538415	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538416	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538417	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538418	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538419	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538456	WH1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538530	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538547	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538549	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538550	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538573	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538575	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538606	H1E	Wuxi Diesel	FAW CA TRUCKS, & ZK BUSES		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3502500						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538626	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538627	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538628	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538629	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538631	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		<i>H1C-H1</i>				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538632	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538633	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538636	HX50				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		ND		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538646	WH1E	MAN	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538675	H1E	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538677	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538680	HX40W	Scania	TRUCK & BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538678						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538685	HX40W	Scania	TRUCK & BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538678						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538686	HX40W	Scania	TRUCK & BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538678						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538688	HX35G	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538697	HX40W	Cummins Inc.	CASE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538699	HX40W	Cummins Inc.	CASE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538703	HX35G	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538706	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538707	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538717	HX55				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533542						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538718	HX55				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX55			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533542						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538731	HX35G	Cummins Inc.	GAS		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538760	H1C	Cummins Inc.	MARINE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538778	H1E	Cummins Inc.	MARINE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538781	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538821	H2D	Perkins			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524998		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538828	H1E	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538830	H1E	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538840	H1C	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538853	HX40W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538857	HX40W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538859	HX50				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3534287		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533052						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538860	HX50				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3534287		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533052						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538861	HX50				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3534287		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533052						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538866	HX35W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538867	HX35W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538869	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538870	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538871	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538872	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538874	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538875	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538877	HX35W	Cummins Inc.	FD ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538878	HX35W	Cummins Inc.	FD ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538879	HX35W	Cummins Inc.	FD ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538880	HX35W	Cummins Inc.	FD ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538882	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538884	HX35W	Cummins Inc.	AUTOMOTIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538906	H2D	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3538935	HX35	TCL	125LM/HCV		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539009	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539010	HX35W	Cummins Inc.	AUTOMOTIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539012	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539013	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539014	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539015	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539016	HX40W	Cummins Inc.	FD ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539019	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539020	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539022	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539023	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539024	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539127	HX40W	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3535198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539149	HX40	Cummins Inc.	RAIL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539208	HX40W	Cummins Inc.	DENNIS EAGLE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539262	HX35W	Cummins Inc.	FD FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539263	HX35W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539264	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539265	HX40	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539303	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539310	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3521863		3519336		3534947		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539311	HX40W	Cummins Inc.	DSV COACH		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539312	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539331	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539344	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539370	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539372	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532634						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539373	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539374	HX35W	Cummins Inc.	DODGE RAM		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539429	WH1C	DFM	TRUCK & XMQ BUSES		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599640		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539448	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539450	HX35	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539462	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539463	HX35W	Cummins Inc.	FD ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539464	HX35W	Cummins Inc.	AUTOMOTIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539465	H1E	Cummins Inc.	CONSTRUCTION		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539467	H1C	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539469	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539471	H1E	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539473	H1C	Cummins Inc.	MARINE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599638		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539477	HX40W	Cummins Inc.	EURO 2		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539505	HX35				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539637	HX40W	Scania	TRUCK & BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538678						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539654	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539655	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539656	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539657	HX35	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539658	HX35	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539679	HX35	DHI	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599590		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3599890						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539698	HX35	Cummins Inc.	KOMATSU		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539694						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539699	HX35	Komatsu	CD60R, PC220		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539694						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539700	HX35	Cummins Inc.	KOMATSU		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539694						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539700	HX35	Komatsu	PC220		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539694						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539803					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3539805		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539837	HX40W	Volvo	FM7 TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539843						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539839	HX40W	Volvo	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539843						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539840	HX40W	Volvo	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539843						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539841	HX40W	Volvo	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539843						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539842	HX40W	Volvo	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539843						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539846	HX30	Cummins Inc.	KOMATSU		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539898						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539862	HX40W	Cummins Inc.	NEWFLYER BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539911	HX35W	Cummins Inc.	CHRYSLER ECLIPSE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539912	HX35W	Cummins Inc.	CHRYSLER ECLIPSE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3539956	WH1C	DFM	TRUCK & XMQ BUSES		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599640		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3545515	4LGK	Iveco			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3500433		59618		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3500717						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3545643	H2C				
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522773		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3545901	H2D				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3545915	H2D	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3546847	H2C				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580148	H2D	Perkins			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580214	H2D	Mercedes Benz	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580253	H1E	Mercedes Benz			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599640		3522879		3537204		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3526562						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580263	H2D				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528638						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580266	H1E	Mercedes Benz	TRUCK -TRACT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599640		3522879		3537204		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3526562						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580274	H1E	Mercedes Benz	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599640		3522879		3537204		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3526562						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580552	H2D	Raba			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524808		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580714	H2C	Raba			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503304		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580790	H2D	MAN	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3580808	H2D				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590022	HX30	Cummins Inc.	KOMATSU		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX30			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539898						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590032	HX35	Cummins Inc.	KOMATSU		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539694						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590080	H1E	Cummins Inc.	ZANELLO AGRICULTURAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590081	H1E	Cummins Inc.	ZANELLO AGRICULTURAL	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3522880		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530591					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590082	H1E	Cummins Inc.	ZANELLO AGRICULTURAL	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3522880		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530591					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590083	H1E	Cummins Inc.	ZANELLO AGRICULTURAL	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3522880		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530591					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590091	HX35	Cummins Inc.	FD	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590093	HX35	Cummins Inc.	FD ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590101	HX35	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590102	HX35	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590103	HX35	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590105	HX35W	Cummins Inc.	MY99 APPLICATION		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590145					
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3539805		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590156	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590253	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590254	HX35W	Cummins Inc.	THOMAS BUS ENGINE	
CHRA		Repair Kit H1C-H1	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590273	HX55	Volvo		
CHRA		Repair Kit HX55	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3593686		3533543		3528096	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3590231					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590285	HX40G	Cummins Inc.	GAS ENGINE NABI BUS	
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599592		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3536452					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590340	HX40W	Scania		
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3594833		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3538678					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590343	HX40W	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538678						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590344	HX40W	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538678						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590346	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590385	HX50W	Perkins	Eagles		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3528251		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528638						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590395	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590407	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590421	HX50	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593688		3528251		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591794						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590495	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590536	WH1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590537	WH1E	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599646		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3531277						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590538	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594834		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537965						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590539	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594834		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537965						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590540	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590541	HX40W	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590542	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590574	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590590	HX35G	Volvo	GAS	
CHRA		Repair Kit H1C-H1	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3590419		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3592561					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590599	HX40W	Volvo	TRUCK	
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3594835		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3539843					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590678	HX40W	Cummins Inc.	EURO 2	
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599591		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3590686	HX40W	Cummins Inc.	GAS ENGINE (ERF)	
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599592		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3536452					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590794	HX35	TCL	125LM/HCV		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590807	HX35W	Leyland Daf			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3590850	HX40W	Volvo	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536611						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591024	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591025	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591047	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591048	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591049	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591050	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591051	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591052	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591053	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591054	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591055	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591056	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591057	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591058	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591059	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591079	HX55	Volvo	VN TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3590231						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591112	HX50W	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3528251		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3592695						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591180	HX40W	Scania	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591193	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591247	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591249	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591274	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591275	HX40W	MAN	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591363	HX35	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591364	HX35	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591379	HX40W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591380	HX40W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591382	HX40W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591426	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591457	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591458	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591459	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591460	HX40W	Cummins Inc.	ISC ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591461	HX35	Daewoo	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599590		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3599890						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591608	H2C	Renault			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503304		3528251		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591609	4LGK	Iveco			
CHRA			<i>Repair Kit</i>	-	<i>Heatshield</i>	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503704		3527176		59618		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3504220						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591620	H2D	Iveco	TRUCK-SPR RANGE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591621	H2D	Iveco	190.36, 330.36 TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591622	H2D	Iveco	190.36, 330.36 TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591623	H2D	Iveco	330.36 BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591651	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591686	H2D	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591138						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591727	HX40G	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591986						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591729	HX40G	Volvo	B10M TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591986						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591732	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591733	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591734	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591735	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591768	HX50				
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3534856		3591772		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528096						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591769	HX50				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3534856		3591772		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3528096						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591777	HX50	Scania			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3534287		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591779	HX50	Scania			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3534287		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591794						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591780	HX50	Scania			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3534287		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591794						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591783	HX50	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593688		3528251		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591983						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591807	HX40W	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591811						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591808	HX40W	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591811						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591809	HX40W	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591811						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591849	HX40W	Volvo	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3592136						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591850	HX40W	Volvo	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3592136						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591851	HX40W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591852	HX40W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591949	HX55				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX55			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3533542						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591969	H2D	Volvo			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591970	H2D	Volvo			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H2B			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591976	HX35	TCL	GENSET		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3591987	HX35G	Cummins Inc.	ION BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592015					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3539805		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592016	HX30	Cummins Inc.	KOMATSU / ELITE IND		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592019					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3539805		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592020	HX30	Cummins Inc.	KOMATSU / ELITE IND		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592040	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592041	HX35W	Cummins Inc.	FD ENCE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592052	HX40	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592053	HX40	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592054	HX40	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592055	HX40	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592056	HX40	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592065	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592066	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592069	HX40	MAN	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592070	HX40	MAN	BUS (HIZONTAL REAR)		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592102					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3539805		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592103					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592104					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592109					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3539805		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592110	HX30	Cummins Inc.	ELITE IND		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592111	HX30	Cummins Inc.	ELITE IND		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592112	HX30	Cummins Inc.	KOMATSU / ELITE IND		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592113					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3539805		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592121					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3539805		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592122					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30	Cummins Inc.	KOMATSU / ELITE IND		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592123					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30	Cummins Inc.	ELITE IND		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592124					
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX30	Cummins Inc.	ELITE IND		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592125					
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3539805		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592126					
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX30	Cummins Inc.	EURO 2 ENGINE		
		HX30				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599693		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030799						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592200					
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX35W	Cummins Inc.			
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592201					
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX35W	Cummins Inc.	FD ENCE		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592202	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592220	HX40W	Cummins Inc.	Cummins BRAZIL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592221	HX35	Cummins Inc.	MILITARY		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592222	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592223	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592224	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592225	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592226	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592252	HX40W	Cummins Inc.	LOADAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592372	HX40W	Cummins Inc.	HYUNDAI		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592375	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592504	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592505	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592506	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592507	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592508	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592509	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592510	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592511	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592526	HX35W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592527	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592587	HX40W	Volvo	FM7 TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3539843						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592588	HX40W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592590	HX40W	Volvo	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536611						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592668	HX40W	Cummins Inc.	NEWFLYER BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592671	HX35	TCL	HCV		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592723	HX40	MAN	Tract		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592726	HX40	MAN	Tract		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592753	HX40W	Volvo	VN TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592754	HX40W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592755	HX40W	Volvo	WG TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3592756	HX40W	Volvo	VNM TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3592759	HX40W	Volvo	TRUCK	
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3594835		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3591378					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3592760	HX40W	Volvo	WXLL TRUCK	
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3594835		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3591378					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3592767	HX35W	Cummins Inc.	MY99.5 APPLICATION	
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3592885	HX35W	Cummins Inc.		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593026	WH1E	Yuchai	DFM TRUCKS	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599638		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3502500					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593089	HX30	Cummins Inc.	ELITE IND	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX30			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599693		3539805		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
4030799					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593090	HX30	Cummins Inc.	KOMATSU / ELITE IND	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX30			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599693		3539805		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
4030799					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593093	HX40W	Cummins Inc.	ISC F MACK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599550		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3537112					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593143	HX35	TCL	EXCAVAT-1	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599588		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593149	HX50	Scania		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3593688		3528251		3528096	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3591983					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593185	HX35	Daewoo		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599590		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3599890					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593202	HX40W	Volvo	B10B, B10M, B10L TRUCK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3594833		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3596298					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593203	HX40W	Volvo	B10B, B10M, B10L TRUCK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3594833		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3596298					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593204	HX40W	Volvo	B10B, B10M, B10L TRUCK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3594833		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3596298					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593211	HX35	Cummins Inc.	KOMATSU	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599593		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
4041316					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593287	HX35	Cummins Inc.		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593289	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593316	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599590		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593325	H2C	Perkins	BRITISH RAIL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3503305		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593334	HX40W	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593341	HX35	TCL	EXCAVAT-5	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599588		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593349	WH1E	Wuxi Diesel	FAW CA TRUCKS	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599638		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3502500					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593359	WH1E	Wuxi Diesel	FAW CA TRUCKS	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599638		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3502500					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593423	HX40W	Volvo	B10B, B10M, B10L TRUCK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3596097		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
4039294					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593425	HX40W	Iveco	COMBINE HARVESTER	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3594834		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3537112					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593468	HX40W	Cummins Inc.	BUS	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599550		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3537112					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593565	HX40W	Cummins Inc.	EURO 2	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599591		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3593569	HX35W	Cummins Inc.	Daf	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532630					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593594	HX40W	MAN	BUS (HORIZONTAL REAR)		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593606	HX55	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3535983		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3535704						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593607	HX55	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3535983		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3535704						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593651	HX35	Cummins Inc.	DINA ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593655	HX40W	Cummins Inc.	KOMATSU WHEELED LOADER	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599592		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593658	H1C	Cummins Inc.	MARINE-WET GENSET	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3521863		ND		3524947	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530591					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593676	HX35W	Cummins Inc.	IBS ENGINE	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3593681	HX35	Cummins Inc.	GENSET MARINE	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593879	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593888	HX35	Daewoo	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593894	HX50	Man			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3534287		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593895	HX50	Man	F2000 TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3596134		3534287		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3592089						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593919	HX40	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593921	HX40	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593930	HX35W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3594271						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593932	HX35W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3594271						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593933	HX35W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3594271						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593934	HX35W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3593977	HX40W	Volvo	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536611						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594002	HX40W	MAN	BUS (HIZONTAL REAR)		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594278	WH1E	Daewoo	AUTOMOTIVE/BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594290	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594310	HX35	TCL	EURO 2 HCV		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594323	HX40W	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3594473	HX40W	Cummins Inc.	AGCO	
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599550		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3537112					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3594596	HX40W			
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599592		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3594596	HX40W	Cummins Inc.	EURO 2	
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599592		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	3594621	H2D	Scania		
CHRA		Repair Kit H2B	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3524808		3528251		62564	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3528638					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594635	HX35W	Cummins Inc.	KAMAZ SO14077		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594801	HX40W	Cummins Inc.	CASE TRACT		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594809	HX50	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3531763		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537051						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594810	HX50	Cummins Inc.	BOMAG		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3531763		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537051						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594853	HX40G	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591986						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3594855	HX40W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591986						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595000	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595001	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595002	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595003	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595004	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595005	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595006	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595007	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595008	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595009	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595010	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595011	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595012	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595013	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595014	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595015	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595016	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595017	HX40W	Cummins Inc.	NOVA BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595019	HX35	Telco			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595110	HX35	Telco	GENSET 50KVA		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599590		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595160	HX35W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027249						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595201	HX32	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595202	HX32	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3539805		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4030798						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595239	HX40W	MAN	BUS (VERTICAL REAR)		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595275	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595387	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595508	HX40	CIL	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595809	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595811	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595812	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595814	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595822	HX40W	Cummins Inc.	DENNIS COACH		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595858	HX35	Cummins Inc.	INDUSTRIAL RATINGS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3532312		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027249						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595859	HX35	Cummins Inc.	INDUSTRIAL RATINGS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3532312		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027249						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595892	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595915	HX40W	Volvo	VN TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595925	HX35	Onan			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3595938	HX40W	MAN	BUS (VERTICAL REAR)		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3593878						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3596018	HX35	Telco	HIGH TQUE (SFC)	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599588		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
4027850					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3596023	HX35G	Volvo	FL6 TRUCK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3519336		NA	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3596083	HX40W	Cummins Inc.	FREIGHTLINER	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599550		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3537112					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3596084	HX40W	Cummins Inc.	FREIGHTLINER	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599550		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3537112					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596085	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596086	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596087	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596088	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596122	HX50W	Daewoo	CNG Bus		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3528251		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3592695						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596125	HX35W	Volvo	Bus		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3596270						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596126	HX35W	Volvo	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3596270						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596127	HX35W	Volvo	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3596270						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596138	HX40W	Volvo	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594835		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536611						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596141	HX40W	Cummins Inc.	DENNIS TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596151	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596277	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3596330	HX35	Cummins Inc.	EXCAVAT	
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532630					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3596350	WH1E	DFM	EQ TRUCKS & XMS BUSES	
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599642		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530592					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3596352	WH1E	DFM	EQ TRUCKS & XMQ BUSES	
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599643		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530592					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3596390	HX40W	Cummins Inc.	BUS	
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599591		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596408	HX40W	Cummins Inc.	COMBINE HARVESTER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596415	HX40W	Cummins Inc.	CASE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596420	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596421	HX40W	Cummins Inc.	ISC ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596422	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596423	HX40W	Cummins Inc.	ISC ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596424	HX40W	Cummins Inc.	ISC ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596425	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596426	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596427	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596428	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596429	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596430	HX40W	Cummins Inc.	ISC ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596431	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596432	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596630	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027249						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596631	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596632	HX35W	Cummins Inc.	KCEC		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596633	HX35W	Cummins Inc.	KCEC		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596668	HX35	Cummins Inc.	INDUSTRIAL RATINGS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596691	HX35	Telco	HIGH TQUE (SFC)		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596713	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596714	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596715	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596722	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596723	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596724	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596725	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596726	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596727	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596728	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596729	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596730	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596731	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596732	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596733	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596734	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596735	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596736	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596737	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3596746	HX40	MAN	STAR TRUCK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3591190					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3596755	WH1C	DFM	TRUCK & XMQ BUSES	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599640		3519336		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530592					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3596756	WH1C	DFM	TRUCK & XMQ BUSES	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599640		3519336		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530592					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3596928	HX40	Cummins Inc.		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599591		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596945	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596947	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596949	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4041316						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596950	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4041316						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596953	HX35	Cummins Inc.	AUTOMOTIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4041316						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596955	HX35	Cummins Inc.	AUTOMOTIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4041316						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596980	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596990	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596991	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596992	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3596993	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597024	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597068	HX35	Cummins Inc.	GENSET 125KVA		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597077	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597078	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597079	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597082	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597083	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597085	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597099	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3597111	HX35W	Cummins Inc.	KCEC	
CHRA		<i>Repair Kit</i> H1C-H1	-		Heatshield
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599651		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
4027249					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3597132	HX40W	Cummins Inc.	FD TRUCK	
CHRA		<i>Repair Kit</i> HX40	-		Heatshield
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599550		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3537112					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3597183	HX40W	MAN	BUS (VERTICAL REAR)	
CHRA		<i>Repair Kit</i> HX40	-		Heatshield
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599593		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3591190					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
Holset	3597243	HX40W	Cummins Inc.	BUS	
CHRA		<i>Repair Kit</i> HX40	-		Heatshield
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599591		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597245	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597247	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597249	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597281	HX40W	MAN	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597309	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597310	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597311	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597336	HX40W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597373	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597373	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597374	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597375	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3597376	HX40W	Cummins Inc.	MEXICAN TRUCK		
CHRA		Repair Kit HX40	-	Heatshield		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3597397	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		Repair Kit HX40	-	Heatshield		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3597398	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		Repair Kit HX40	-	Heatshield		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3597399	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		Repair Kit HX40	-	Heatshield		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597400	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597402	HX40G	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597404	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597405	HX40W	Cummins Inc.	NABI BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597407	HX40G	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597409	HX40W	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597412	HX35G	Cummins Inc.	NATURAL GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3532312		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597413	HX35G	Cummins Inc.	ION BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3532312		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597415	HX35G	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597417	HX35G	Cummins Inc.	GAS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597420	HX35G	Cummins Inc.	EMERALD		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597423	HX35G	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597424	HX35G	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597425	HX35G	Cummins Inc.	GAS ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597474	HX35	Telco	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027850						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597477	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597500	HX40	MAN	Tract		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3538198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597502	HX40W	MAN	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597509	HX35W	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591801						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597577	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597578	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597579	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597580	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597582	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597583	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597585	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597587	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597589	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597590	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597591	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597593	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597594	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597596	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597597	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597599	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597600	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597601	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597603	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597635	HX40W	Cummins Inc.	NEW FLYER BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597636	HX40W	Cummins Inc.	NEW FLYER BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597651	HX35W	Cummins Inc.	HOUCHIN AEROSPACE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597654	HX50	Scania			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3597653		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591983						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597656	HX50	Scania			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3597653		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591983						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597660	HX50	Scania			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593688		3528251		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591983						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597661	HX50	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX50				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593688		3528251		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591983						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597728	HX55				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027087						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597729	HX55	Scania			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027087						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597730	HX55				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027087						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597759	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597761	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597762	HX40W	Cummins Inc.	FIRE TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597788	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597808	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		ND		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597809	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597810	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597811	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597812	HX40W	Cummins Inc.	Cummins APPLICATION		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597826	HX40W	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597863	HX35	TCL	GENSET (118KVA)		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597912	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597914	HX35	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3597931	HX40W	Cummins Inc.	CX330 EXCAVAT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598045	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598062	HX40W	Cummins Inc.	6C		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3590929		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598064	HX40W	Cummins Inc.	6C		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3590929		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598066	HX40W	Cummins Inc.	ISC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598067	HX40W	Cummins Inc.	6C		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598068	HX40W	Cummins Inc.	ISC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598074	HX40W	Cummins Inc.	COMBINE HARVESTER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598090	HX35W	Cummins Inc.	QSC TIER 2		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598110	HX35	TCL	TIPPER EURO-II		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598126	HX35	Daewoo	GAS GENSET		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599589		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3598668						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598176	HX35	Cummins Inc.	ELITE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598239	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598240	HX40W	Cummins Inc.	ISL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598263	HX40W				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598327	HX40W	Cummins Inc.	COTTON PICKER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598338	HX35	Daewoo	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3599890						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598339	HX35	Daewoo	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3599890						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598340	HX35	Daewoo	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3599890						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598341	HX35	Daewoo	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3599890						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598392	HX35G	Daewoo	CNG BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598566	HX35	TCL	SE/SK TRUCKS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598682	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598683	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598702	HX35	Cummins Inc.	INDUSTRIAL RATINGS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598715	HX40W	Cummins Inc.	JCB		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598736	HX40W	Cummins Inc.	FD TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598909	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598920	HX40	Cummins Inc.	N/a		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598926	HX35	TCL	EXCAVAT		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598945	HX52	Volvo			
CHRA			<i>Repair Kit</i>	-	<i>Heatshield</i>	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3592602		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3590231						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598946	HX52	Volvo			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3592602		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3590231						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598947	HX52	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3592602		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3590231						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598948	HX52	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593686		3592602		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3590231						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3598965	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599026	HX40	Cummins Inc.	FD REPTO		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599079	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599086	HX40W	Cummins Inc.	INDUSTRIAL (CASE)		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599108	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599109	HX35	Cummins Inc.	WHEEL LOADER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599111	HX40	Cummins Inc.	NATURAL GAS ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3536452						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599113	HX35	Cummins Inc.	KOMATSU D58		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599152	HX35	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599155	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599173	HX40W	Cummins Inc.	FD REPTO		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599178	HX40W	JI Case	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599179	HX40W	JI Case	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599180	HX40W	Cummins Inc.	CASE TRACT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599184	HX35	Komatsu			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4041316						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599185	HX35	Cummins Inc.	ZANELLO AGRICULTURAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4041316						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599186	HX35	Cummins Inc.	REPOWER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4041316						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3599206	WH1E	Daewoo	AUTOMOTIVE/BUS	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599643		3522879		3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3530592					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3599260	HX40W	MAN	BUS (VERTICAL REAR)	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599593		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3591190					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3599261	HX40	MAN	TRUCK	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3591190					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	3599280	HX40W	MAN	BUS	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599594		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3591190					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599309	HX35	Eicher	EURO 1		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3596181						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599334	HX40W	Cummins Inc.	PETERBILT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599335	HX40W	Cummins Inc.	PETERBILT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599336	HX40W	Cummins Inc.	ISC PETERBILT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599359	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599370	HX40W	Iveco	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599371	HX40W	Iveco	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599386	HX40W	Iveco	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599475	HX40W	Cummins Inc.	CASE TIGERCAT		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599476	HX40W	Cummins Inc.	CASE TIGERCAT		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599478	HX40W	Cummins Inc.	CASE TIGERCAT		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599480	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599492	HX35G	Cummins Inc.	WESTPT B-PLUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599493	HX35G	Cummins Inc.	WESTPT B-PLUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599601	HX40W				
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599602	HX40W	Cummins Inc.	LMRO		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599607	HX35	Cummins Inc.	KCEC D41 BULLDOZER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599686	HX35	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599691	HX40W	Iveco	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599718	HX35	TCL	BUS (FRONT)		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3599726	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3599728	HX35W	Cummins Inc.	6BTE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3599757	HX40W	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599591		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591801						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	3599799	HX35W	Cummins Inc.	CNH APPLICATION		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599830	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599865	HX35	TCL	BUS (REAR)		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599881	HX40W	MAN	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3599922	HX35W	Cummins Inc.	IPA / KCEC		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802289	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802303	H1E				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802304	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802310	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599639		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802417	H1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802598	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802600	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599641		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802676	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802683	WH1C	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599644		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802684	WH1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599643		3522879		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530592						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802779	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802782	HX40W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3802910	H1E	Cummins Inc.	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3525687		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3803024	H2D	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524996		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3525199						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3803806	H1C	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3518201		3519336		3503945		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3519533						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	3919217	H1E	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599642		3522880		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4027206	H2D	RVI	R365		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		62564		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3519533						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4027573	H2D	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3524997		3522773		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3191772						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4027733	H2D	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H2B				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522773		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4031502	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4031503	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4031504	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4031505	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4031506	HX35	TCL			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4031508	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4031509	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4031510	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4031517	HX40W	FML	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4032109	HX40G	Volvo			
CHRA		Repair Kit HX40	-	Heatshield		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4032110	HX40G	Volvo	B10M TRUCK		
CHRA		Repair Kit HX40	-	Heatshield		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4032220	HX35W	Fd Otosan	TRUCK		
CHRA		Repair Kit H1C-H1	-	Heatshield		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4035024	HX35W	Cummins Inc.	TIER 2		
CHRA		Repair Kit H1C-H1	-	Heatshield		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035026	HX40	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035036	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035037	HX35W	Cummins Inc.	METSO DYNAPAC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035038	HX35W	Cummins Inc.	KCEC		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035063	HX40W	Cummins Inc.	LMRO		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035119	HX35	Daewoo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3535198						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035158	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035190	HX35	DFM	TRUCK & XMQ BUSES		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3530591						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035200	HX35W	DFM	B180		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035207	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035217	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035296	HX35W	Cummins Inc.	HHI		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035297	HX35W	Cummins Inc.	TIER 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035330	HX40W	MAN	Tract		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035374	HX35	Cummins Inc.	EXCAVAT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035376	HX35W	Cummins Inc.	EXCAVAT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027882						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035415	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035423	HX35	Cummins Inc.	KCEC/IPA FD80 FKLIFT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035455	HX35	Daewoo	EXCAVAT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599590		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3599890						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035463	HX40	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035464	HX40	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035524	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035525	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035528	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4035529	HX35W	Cummins Inc.			
CHRA			Repair Kit H1C-H1	-		Heatshield
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4035556	HX35W	Cummins Inc.	EURO 2 CITY BUS ENGINE		
CHRA			Repair Kit H1C-H1	-		Heatshield
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4035627	HX35G	Volvo	GAS		
CHRA			Repair Kit H1C-H1	-		Heatshield
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599593		3519336		3522801		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3592561						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4035628	HX35	Cummins Inc.	REPOWER		
CHRA			Repair Kit H1C-H1	-		Heatshield
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4041316						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035630	HX35	Cummins Inc.	ELITE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532634						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035632	HX40	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035635	HX40	MAN	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3591190						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035650	HX40W	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035653	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3535359		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035655	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035761	HX35	Cummins Inc.	ELITE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599588		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4041316						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035773	HX35G	Cummins Inc.	WESTPT B-PLUS		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035809	HX35	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035883	HX35W	Cummins Inc.	METSO DYNAPAC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035921	HX38G	Iveco	CNG		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035928	HX38G	Iveco	GAS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4035976	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3594833		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036034	HX35	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036143	HX35W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4035699		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532629						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036172	HX35	Cummins Inc.	GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036194	HX35	Cummins Inc.	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036245	HX40W	DHIM	AUTOMOTIVE/BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036247	HX40W	Daewoo	AUTOMOTIVE/BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036282	HY55V	IVECO	Curs 13		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3592938 42-002		3590433 41-002		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036325	HX35	Cummins Inc.	FD70 CX & DX FKLIFT		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036391	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036398	HX35W	Cummins Inc.	TIER 2		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036437	HX52				
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3592602		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3598984						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036438	HX52				
CHRA			<i>Repair Kit</i>	-	<i>Heatshield</i>	
<i>CW OE Code</i>		<i>SW OE code</i>			<i>BP OE Code</i>	
3593629 42-001		3592602			3528096	
<i>BH OE Code</i>		<i>Act OE Code</i>			<i>Vnt OE code</i>	
3598984						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036458	WH1E	Volvo			
CHRA			<i>Repair Kit</i>	-	<i>Heatshield</i>	
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>			<i>BP OE Code</i>	
3599646		3535359			3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>			<i>Vnt OE code</i>	
3520574						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036460	WH1E	Volvo	FL7, FS7 TRUCK		
CHRA			<i>Repair Kit</i>	-	<i>Heatshield</i>	
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>			<i>BP OE Code</i>	
3599646		3535359			3522801	
<i>BH OE Code</i>		<i>Act OE Code</i>			<i>Vnt OE code</i>	
3520574						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036470	HX35	Cummins Inc.	GENSET		
CHRA			<i>Repair Kit</i>	-	<i>Heatshield</i>	
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>			<i>BP OE Code</i>	
3599651		3519336			3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>			<i>Vnt OE code</i>	
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	4036514	HX35	Cummins Inc.	RAILCAR	
CHRA		Repair Kit H1C-H1	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	4036523	HX40W	Daewoo	AUTOMOTIVE/BUS	
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3522879		NA	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	4036550	HX35W	Cummins Inc.	AGCO	
CHRA		Repair Kit H1C-H1	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599650		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532630					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck
Holset	4036628	HX40W	Cummins Inc.	OTTOWA TRUCK	
CHRA		Repair Kit HX40	-	Heatshield	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599592		3522879		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
3532632					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036628	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036629	HX35W	Cummins Inc.	OTTOWA TRUCK		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036731	HX35W	Cummins Inc.	HHI		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036812	HX35W	Cummins Inc.	JCB		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599650		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532630						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036819	HX35	Telco	GENSET 75KVA		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599590		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036888	HX40W	Cummins Inc.	BOMBARDIER SNOW		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036903	HX55				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX55			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3590231						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036904	HX50				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX50			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3533543		3528096		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3590231						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036950	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4035380		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036978	HX40W	Cummins Inc.	CNH 4WD TRACT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3191772						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4036979	HX40W	Cummins Inc.	Tract		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599550		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3191772						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037120	HX40W	Cummins Inc.	DENNIS BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037121	HX40W	Cummins Inc.	BIN WAGGON		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037122	HX40W	Cummins Inc.	DENNIS BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037254	HX35W		MEXICO BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037256	HX38G	Iveco	GAS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599651		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3534487						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037297	HX40W	Cummins Inc.	DENNIS BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4036122		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037308	HX35	TCL			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599594		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037374	HX35	Cummins Inc.	EXCAVAT		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037470	HX35	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037497	HX35	TML			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599590		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027850						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037686	HX40W	Cummins Inc.	ENCE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4035380		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3191772						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037687	HX40W	Cummins Inc.	ENCE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4035380		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037688	HX40W	Cummins Inc.	ENCE		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4035380		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037689	HX40W	Cummins Inc.	FREIGHTLINER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4035380		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037690	HX40W	Cummins Inc.	NEWFLYER BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4035380		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037691	HX40W	Cummins Inc.	ENCE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4035380		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037703	HX40	CIL	Genset		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037704	HX40	CIL	GENSET		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599592		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037963	HX35				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599590		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
4027850						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037984	HX40W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037985	HX40W	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037986	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037987	HX40W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037988	HX40W	Cummins Inc.	KENWTH		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037989	HX40W	Cummins Inc.	KENWTH		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
4035380		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3537112						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037990	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037991	HX40W	Cummins Inc.	KENWTH		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4037997	HX40W	Cummins Inc.	ENCE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038045	HX40W	Cummins Inc.	KIA TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker <i>Holset</i>	Turbo OE 4038048	Turbo Model HX40W	Fitted to make Cummins Inc.	Fitted to model TRANSIT BUS	Truck	
CHRA		<i>Repair Kit</i> HX40	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker <i>Holset</i>	Turbo OE 4038049	Turbo Model HX40W	Fitted to make Cummins Inc.	Fitted to model TRANSIT BUS	Truck	
CHRA		<i>Repair Kit</i> HX40	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker <i>Holset</i>	Turbo OE 4038051	Turbo Model HX40W	Fitted to make Cummins Inc.	Fitted to model TRANSIT BUS	Truck	
CHRA		<i>Repair Kit</i> HX40	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker <i>Holset</i>	Turbo OE 4038052	Turbo Model HX40W	Fitted to make Cummins Inc.	Fitted to model TRANSIT BUS	Truck	
CHRA		<i>Repair Kit</i> HX40	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038053	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038054	HX40W	Cummins Inc.	NEW FLYER BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038057	HX40W	Cummins Inc.	TRANSIT BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038209	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038210	HX35	Cummins Inc.			
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038211	HX35W	Cummins Inc.	TIER 3		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038254	HX38G	Iveco	AGA BUS		
CHRA			<i>Repair Kit</i>	-	<i>Heatshield</i>	
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038287	HX35W	Cummins Inc.	TIER 3		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038288	HX35	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038384	HX35W	Cummins Inc.	CITY BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038478	HX35W	Cummins Inc.	KCEC ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038479	HX35W	Cummins Inc.	WHEEL LOADER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038480	HX35	Cummins Inc.	WHEEL LOADER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038481	HX35	Cummins Inc.	WHEEL LOADER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038482	HX35	Cummins Inc.	KCEC D41 BULLDOZER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038483	HX35	Cummins Inc.	KCEC D41 BULLDOZER		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038526	HX35				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038651	HX40W	Cummins Inc.	Industrial engine		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038774	HX40	CIL	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4038963	HX35	TCL	EXCAVAT		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039044	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039147	HX35W	Cummins Inc.	WHEEL LOADER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039185	HX40W				
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039187	HX40W	Cummins Inc.	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039189	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039191	HX40W				
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			HX40			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039243	HX35	Cummins Inc.	WHEEL LOADER		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039278	HX35	Cummins Inc.	INDUSTRIAL		
CHRA			<i>Repair Kit</i>	-		<i>Heatshield</i>
			H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker <i>Holset</i>	Turbo OE 4039279	Turbo Model HX35	Fitted to make Cummins Inc.	Fitted to model INDUSTRIAL	Truck	
CHRA		<i>Repair Kit</i> H1C-H1	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker <i>Holset</i>	Turbo OE 4039280	Turbo Model HX35	Fitted to make Cummins Inc.	Fitted to model KOMATSU D61	Truck	
CHRA		<i>Repair Kit</i> H1C-H1	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker <i>Holset</i>	Turbo OE 4039282	Turbo Model HX35	Fitted to make Cummins Inc.	Fitted to model AUTOMOTIVE	Truck	
CHRA		<i>Repair Kit</i> H1C-H1	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker <i>Holset</i>	Turbo OE 4039298	Turbo Model HX35W	Fitted to make Cummins Inc.	Fitted to model 1996 OFF HIGHWAY	Truck	
CHRA		<i>Repair Kit</i> H1C-H1	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039330	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039331	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039332	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039333	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039413	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039414	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039546	HX35	Cummins Inc.	POWERGEN		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039578	HX40W	Cummins Inc.	AUTOMOTIVE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4039660	HX35W	Cummins Inc.	6BTE ENGINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4039953	HX35G	Cummins Inc.	WESTPT B-PLUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4039954	HX35G	Cummins Inc.	WESTPT B-PLUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4039963	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039964	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039965	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039966	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039967	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4039968	HX35W	Cummins Inc.	GRADER		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4040043	HX40W	Iveco			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4040246	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4040247	HX40W	Cummins Inc.	INDUSTRIAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4040390	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4040398	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4040613	HX38G	Iveco	AGA BUS		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4040675	HX35W	Cummins Inc.	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4040920	HX35M	Doosan	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4040946	HX35M	MAN	MARINE		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4041277	HX40W	Volvo	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4041278	HX40W	Volvo	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4041279	HX40W	Volvo	VNM TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4041280	HX40W	Volvo	TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4041282	HX40W	Volvo	VN TRUCK		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4041425	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4041427	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4041457	HX35	Telco	EURO 2		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4042252	HX35G	Cummins Inc.	LP GAS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4042258	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4042264	HX35	Cummins Inc.	KOMATSU		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4042667	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4042762	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4042771	HX35	TCL	GENSET (140KVA)		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4042810	HX35W	Cummins Inc.	POWERGEN		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4042992	HX40	Cummins Inc.	ENCAVA INTERCITY BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043411	HX35W	Volvo	Bus		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043413	HX35W	Volvo	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043415	HX35W	Volvo	BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043614	HX35G	Volvo			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043678	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043679	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043685	HX35	Tata Cummins	KVA GENSET		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043802	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043888	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4043957	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4044095	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4044099	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4044104	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4044128	HX35	Cummins Inc.	AGRICULTURAL		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4044325	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4044595	HX35	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4044597	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4044599	HX35W	Cummins Inc.			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4044851	HX35W	Doosan	Front End Loader		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4044890	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3599649		3519336		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4044990	HX40W	Industrial			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		3530923		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
3532632						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

Maker	Turbo OE	Turbo Model	Fitted to make	Fitted to model	Truck	
Holset	4045163	HX40	Kirloskar	FIRE PUMP		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4045173	HX35W	Cummins Inc.	TIER 3		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4045396	HX35W	Cummins Inc.	TIER 3 POWERGEN		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4045428	HX35W	Cummins Inc.	AGRALE BUS		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4045632	HX35	Cummins Inc.	Front End Loader		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	4045700	HX35W	Cummins Inc.	INGERSOLL RAND	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	4045785	HX35	Cummins Inc.	KOMATSU INDUSTRIAL	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	4046265	HX35W	Cummins Inc.	TIER 3	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
ND		3519336		NA	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck
<i>Holset</i>	4046281	HX35	Cummins Inc.	INDUSTRIAL	
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>	
		H1C-H1			
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>	
3599649		3519336		3530923	
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>	
ND					
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>
<i>VSR Balance calibration</i>					

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4046892	HX40G	Cummins Inc.	NATURAL GAS ENGINE		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4046928	HY40V	IVECO	CURS 8 - F2B		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3598705		3595129		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4046943	HY55V	IVECO	CURS 10		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3593629 42-001		3597275		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4046945	HY55V	IVECO	CURS 13		
CHRA		<i>Repair Kit</i>	-	<i>Heatshield</i>		
		HX55				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
3592938 42-002		3590433 41-002		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4049894	HX40W	MAN			
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		HX40				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3522879		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						

<i>Maker</i>	<i>Turbo OE</i>	<i>Turbo Model</i>	<i>Fitted to make</i>	<i>Fitted to model</i>	Truck	
<i>Holset</i>	4049897	HX35	Cummins Inc.	KOMATSU		
CHRA		<i>Repair Kit</i>	-		<i>Heatshield</i>	
		H1C-H1				
<i>CW OE Code</i>		<i>SW OE code</i>		<i>BP OE Code</i>		
ND		3519336		NA		
<i>BH OE Code</i>		<i>Act OE Code</i>		<i>Vnt OE code</i>		
ND						
<i>Actuat Calibration1</i>	<i>Actuat Calibration2</i>	<i>Actuat Calibration 3</i>	<i>Actuat Calibration 4</i>	<i>Delta</i>	<i>Epsilon</i>	
<i>VSR Balance calibration</i>						